

in Enterprise, Ala. While driving his 2003 GMC Yukon, he fell asleep and the vehicle drifted off the right side of the road. After over-correcting to the left, he lost control of the vehicle, crossed

and entered the grassy Soldier had completed assessment for this trip.

in a motorcycle accident July 16 at 1330 local in Soldier was operating a 2006 Suzuki M50 when controlled intersection. A 2005 Hyundai Santa crossed into the path of the Soldier's motorcycle resulting in a collision. The Soldier was taken to a local medical center where he died as a result of his injuries. He was wearing a DOT approved half-helmet,

had attended the Armyapproved Motorcycle Safety Foundation Course seven years ago and had completed the Commander's Safety Course last year.

COST: 1 Soldier Killed

► A Soldier was injured in a motorcycle accident July 16 at 1500 local near Heidelberg, Germany. The Soldier was operating his motorcycle in a group ride when his motorcycle collided with other motorcycles in the group.

COST: 1 Soldier Injured

gun truck in a convoy escorting third country nationals. The Soldier's vehicle was the second vehicle in a three-vehicle convoy. As the second vehicle approached the main gate of a forward operating base, the third vehicle did not stop and impacted the second vehicle. The impact caused the second vehicle to push forward and impact the lead gun truck causing both to roll.

COST: 1 Soldier Injured

2 Gun Trucks Damaged

https://crc.army.mil

► A Soldier was injured in a multi-Army motor vehicle accident July 18 at 0520 local in Iraq. The Soldier was the gunner





